



NOTE: HAVE BOTH PARTS OF STEAM DOME BOLTED TIGHTLY TOGETHER BEFORE FINAL WELDING TO BARREL. THIS KEEPS FACES FLAT.

BOLER SIDE VIEW
 1 1/2 SCALE LIGHT MOGUL
 SHEET- B1