



4-40 TAP 4 PLCS
LOCATE TO MATCH WITH
HOLES IN RUNNING BOARD

RUNNING BOARD SUPPORT ASSY
1 RH & 1 LH REQUIRED

RUNNING BOARD SUPPORT ASSY.
1 1/2" LIGHT MOGUL
SHEET 35

DRAWN BY PAUL F BRIEN NOVEMBER 1996

